



# ASSEMBLY INSTRUCTIONS FOR #809 & #810--MUSCLE FEEDER



**DIAGRAM A**



**PARTS LIST**

- 2-1/4 X 1" STRAP X 48"
- 4-1 1/4" X 60" LEGS
- 2-1/4 X 1" STRAP X 4"
- 2- 1 1/2" ANGLE RAILS FOR BASKETS
- 2-2" ANGLE RAILS FOR STEPS
- 2- RECTANGLE UNITS FOR POLY FEEDERS
- 4-#204 HAY BASKETS
- 8-5/16 X 1" BOLTS
- 8- 5/16" LOCK NUTS
- 12-#4 HAIR PINS
- 12-5/16 X 2 1/2" CORN PICKER PINS
- 1-INSTRUCTIONS

**STEP #1**

SLIDE ITEMS A, B, AND C OVER ANGLE IRONS (D) AS PICTURED AND SECURE WITH 5/16 CORN PICKER PINS AND HAIR PINS.

**STEP #2**

ATTACH (E) 4" STRAPS USING 5 1/6 X 1 BOLTS AND LOCK NUTS ON TOP OF EACH SIDE OF THE ANGLE IRONS (D).

**NOTE: DIAGRAM A**

**STEP #3**

ATTACH (F) 48" STRAPS USING 5/16 X 1 BOLTS AND LOCK NUTS ON BOTTOM OF EACH SIDE OF THE ANGLE IRONS (D).

**STEP #4**

ADJUST A, B, AND C FOR PROPER SPACING ACCORDING TO SHEEP AND GOAT SIZES.

**STEP #5**

SET HAY BASKETS (IF ORDERED) AND POLY FEEDERS IN BRACKETS AS SHOWN.



**SYDELL INC.**

46935 SD Hwy. 50  
 Burbank, SD 57010  
 (605) 624-4538

[www.sydell.com](http://www.sydell.com)

email: [sydell@sydell.com](mailto:sydell@sydell.com)