

ASSEMBLY INSTRUCTIONS FOR #860-866 DAIRY GOAT FENCELINE AND 2-SIDED FEEDERS

STEP #1

LOOSEN ALL SET BOLTS ON THE 1 1/4 X 2" SQUARE TUBING TO ALL 1" SQUARE TUBING TO SLIDE IN (B-1, C AND SET BOLTS FOR LEGS

STEP #2

NOTE: IF YOU HAVE PURCHASED ADD-ON UNITS FOR EITHER THE FENCELINE OR 2-SIDED FEEDERS THE SOLID ENDS WILL BE ON EITHER END WITH THE ADD-ON POSTS IN THE MIDDLE.

SEE DIAGRAM #1

STEP #3

ON FENCELINE UNITS SLIDE BACK SUPPORT (A) INTO SLEEVES (A) ON THE LEFT SOLID END. THEN INSERT OTHER END OF BACK SUPPORT INTO THE ADD-ON POST OR RIGHT SOLID END.

STEP #4

ATTACH HAY MANGER IN (B-1) AND (B-2) SLEEVES ON SOLID ENDS OR ADD-ON POSTS. THIS STEP IS USED FOR BOTH FENCELINE AND 2-SIDED FEEDERS.

STEP #5

ATTACH STEP SUPPORTS (C) INTO SLEEVES (C).

STEP #6

AFTER ALL HAY MANAGERS AND SUPPORTS ARE INSTALLED SECURE WITH SET BOLTS ON 1 1/4 X 2" SLEEVES. DO NOT OVER TIGHTEN

STEP #7

INSERT PAN (S) FROM ABOVE OPENING OF FEEDERS AND CENTER ON FRAME. SECURE PANS WITH HOSE CLAMPS AS PICTURES IN DIAGRAM 2.

STEP #8

ATTACH STEP (S) USING (2) HOSE CLAMPS PER STEP SEE DIAGRAM 3

STEP #9

LEGS CAN BE ADJUSTED FOR HEIGHT AND THE FEET ARE DESIGNED TO ACCEPT 2 X 4 TREATED BOARDS, BY USING LAG BOLTS TO SECURE FEET TO THE 2 X 4.



SYDELL INC.

46935 SD Hwy. 50

Burbank, SD 57010

(605) 624-4538

www.sydell.com

email: sydell@sydell.com

ASSEMBLY INSTRUCTIONS FOR #860-866 DAIRY GOAT FENCELINE AND 2-SIDED FEEDERS

